

Protection

California Regional Water Quality Control Board

San Diego Region

Internet Address: http://www.swrcb.ca.gov/rwqcb9/ 9174 Sky Park Court, Suite 100, San Diego, California 92123 Phone (858) 467-2952 • FAX (858) 571-6972



October 3, 2003

In Reply Refer to: TSMC:50-1496.05:peass

Certified Mail – Return Receipt Requested

7002 2410 0004 0603 5204 Mr. Jerry Bogaczyk **Chevron Products Company** P.O. Box 2292 Brea, CA 92822-2292

7002 2030 0003 9100 1329 Mr. James C. Silver P.O. Box 326 Julian, CA 92036

7002 2030 003 9100 1343 Ms. Chervl DeWitt P.O. Box 418

Julian, CA 92036

7002 2030 0003 9100 1312 Ms. Roberta H. Green P.O. Box 395 Julian, CA 92036

7002 2030 003 9100 1336 Ms. Lillie and Mr. Willis Slaughter P.O. Box 514 Julian, CA 92036

Ladies and Gentlemen:

ADDENDUM NUMBER 4 TO CLEANUP AND ABATEMENT ORDER **SUBJECT:** NO. 93-49

Directive 9 of Cleanup and Abatement Order (CAO) No. 93-49 requires the dischargers to submit quarterly progress reports on the implementation of the Corrective Action Plan (CAP) for cleanup of the Julian groundwater petroleum hydrocarbon plume. The cleanup alternative selected for implementation in the December 2000 CAP was source reduction by soil vapor extraction (SVE). Construction of the SVE system began in 2001 with system start up in 2002. Specifically, the SVE system connected to extraction wells at the former Chevron, the former Julian Auto Parts, and the Julian Cider Mill was completed and started on June 6, 2002. The SVE system at Norm's Service Station started operation in July 2002.

The current remediation system has been in operation for a little over a year. Although the CAO requires quarterly progress reports on CAP implementation, a semi-annual reporting period is sufficient to summarize remediation progress. Additionally, producing two reports per year instead of four will be less costly to the dischargers.

California Environmental Protection Agency

The energy challenge facing California is real. Every Californian needs to take immediate action to reduce energy consumption. For a list of simple ways you can reduce demand and cut your energy costs, see our Web-site at http://www.swrcb.ca.gov.

Therefore, Addendum No. 4 to CAO No. 93-49 amends Directive 9 as follows:

Directive 9. The dischargers shall submit semi-annual progress reports on the implementation of the Corrective Action Plan in accordance with the following reporting schedule:

Reporting Period	Report Due
January 1 – June 30	July 30
July 1 – December 31	January 30

Parts a through e of Directive 9, which specify the information to be included in the progress reports, are unchanged.

The heading portion of this letter includes a Regional Board code number noted after "In reply refer to:" In order to assist us in the processing of your correspondence please include this code number in the heading or subject line portion of all correspondence and reports to the Regional Board pertaining to this matter.

If you have any questions, please contact Ms. Sue Pease of my staff at (858) 637-5596.

Respectfully,

John H. Robertus
Executive Officer

JHR:jac:sjp

cc:

c:\julian\caoadden#4.doc File # 50.1496.05

The # 30.1490.0.

Mr. Justin Hawkins, Principal Engineer, Secor International, Inc., 2655 Camino Del Rio North, Suite 302, San Diego, Ca 92108

Mr. Kevin Heaton, Senior Hydrogeologist, County of San Diego Department of Environmental Health, Site Assessment and Mitigation Program, P.O. Box 129261, San Diego, CA 92112-9261